



Service List

Contact Us: 1-800-545-9729



Newco's ISO:17025 accredited lab can handle a wide variety of NDT equipment for all your calibration needs. In addition to our calibration laboratory, Newco also travels all over the country to calibrate stationary equipment such as Magnetic Particle Inspection Machines, rack mounted Ultrasonic Testing Equipment, parts drying ovens and baths used in Florescent Particle Inspection Lines, and many others. See the link below for our current services.

No Evaluation Fees. No services rendered until official approvals. Repair services provided as well.

Service	Identifier
Calibration of Light Meter – Dual Sensor	700S10001
Calibration of Light Meter – Three Sensor	700S10002
Calibration of Light Meter – Ultraviolet	700S10003
Calibration of Light Meter – White Light (fc)	700S10004
Calibration of Light Meter – XR1000, XP-2000	700S10006
Calibration of Gauss Field Indicators	700S10007
Calibration of Electronic Gauss Meter	700S10009
Calibration of Shunt Meter	700S10014
Calibration of Mag Machine	700S10015
Calibration of Densitometer	700S10016
Calibration of Area Monitor – X-ray Area Monitor	700S10017
Calibration of Density Strip – X-ray	700S10018
Calibration of Dosimeter – 0-200mR	700S10019
Calibration of Dosimeter – Above 200mR	700S10020
Calibration of Dosimeter – Digital	700S10021
Calibration of UT Gauge / Thickness – All Models	700S10022
Calibration of Eddy Current – Staveley	700S10025
Calibration of Eddy Current (Magnaflux) – ED-520, 530	700S10027
PM for Processor / Tabletop	700S10028
PM for 160kV or less X-Ray Unit	700S10029
PM for 161kV or more X-Ray Unit	700S10030
Calibration of UT Flaw Detector – All Makes/Models	700S10031
Calibration of Rate Alarms – All Personal Alarms	700S10032
Calibration of Quick Break Tester – All Makes/Models	700S10033
Calibration of Shot Duration Timer – All Makes/Models	700S10034
Calibration of Survey Meters – All Makes/Models	700S10035
Calibration of Tam Panel – All Makes/Models	700S10036
Calibration of Yokes	700S10037
Calibration of Pressure Gauge 0-10,000 psi	700S10038
Calibration of Temperature Gauge IR	700S10073
Calibration of Temperature Gauge Liquid	700S10039
Calibration of Calipers and Micrometers	700S10065